Sanitized Copy Approved for Release 2011/07/06 : CIA-RDP78-03642A000700020018-3

CONFIDENTIAL .

FILE ED-175P ASA MOBILE UNIT

16 June 1960

RE TELECON with at the Warehouse concerning the
Ventelator Camera Eye Piece Viewer for the Visoflex Leitz upper
element. This lens appears to have some sort of a fungus on it
which can not be removed with water. Did not try alchol solution
The operation or use of this lens is not presently impared by
this defect; howvere in extreme high humidity conditions the
lens may or may not fog. This lens will be shipped with the present
unit since it does not impare use of the photographic system. It
may be wize to pouch an additional lens for replacement prior to
demonstrating the unit to the customer. This defect was not noticed
until close inspection was carried out prior to packaging.

LBA

25X1

25X1